

1st November 2003

Dear Customer,

Subject: Product Information – DX 195 Caliper Service Kits for Trailer Axles

ArvinMeritor CVA is pleased to announce the launch of the new DX 195 Caliper Service Kits for Trailer Axles.

ArvinMeritor engineers have now developed a new range of service kit to better suit the servicing needs of the DX195 Caliper.

Some kits have been discontinued and kit components have been changed to allow both more economic and safer caliper servicing.

These new kits will be phased in from the 1st November 2003.

For further information or assistance please contact your Customer Service or Sales Representative.

Yours faithfully,

**Andreas Wallner
Product Manager Brakes**



Meritor DX 195 Caliper Service Kits

Introduction



ArvinMeritor is pleased to announce the introduction of a revised product offer for repair kits for servicing DX195 trailer brakes.

All these new kits are suitable for the ROR DX 195 - 33/34, - 51K/52K brakes.

<u>Old Kit Number</u>	<u>Description</u>	<u>New Kit Number</u>	<u>Description / Comments</u>
DSB2A	Brake Pad Kit	MDP5076	Brake Pad Kit



DSB3	Bearing Kit	NLA*	Revised Offer Use Service Caliper [†] or MCK1168 Eccentric Shaft Kit
------	-------------	------	---




* NLA = No Longer Available


** Service Caliper 15224836SR and 15224837SR where appropriate

Distributor Information Sheet
1st October 2003

Old Kit Number	Description	New Kit Number	Description / Comments
DSB5L	Adjuster Kit	NLA*	Use Service Caliper**
DSB5R	Adjuster Kit	NLA*	Use Service Caliper**



DSB6L	Thrust Plate Kit	NLA*	Use Service Caliper**
DSB6R	Thrust Plate Kit	NLA*	Use Service Caliper**




* NLA = No Longer Available



** Service Caliper 15224836SR and 15224837SR where appropriate

Distributor Information Sheet
1st October 2003

<u>Old Kit Number</u>	<u>Description</u>	<u>New Kit Number</u>	<u>Description / Comments</u>
DSB7	Guide Pin Kit	NLA*	Revised Offer MCK1171 Guide Pin Kit



DSB104 Eccentric Shaft & Seal Kit



MCK1168




MCK1192

* NLA = No Longer Available


** Service Caliper 15224836SR and 15224837SR where appropriate

New Service Kit information

MCK1160 (80mm) & MCK1161 (90mm) Lever Kits
Includes all the components required to replace the 80mm and 90mm Levers respectively.



MCK1168 Eccentric Shaft Kit
Includes the eccentric shaft, top and middle bearings, plus all the seals required for the most extensive servicing recommended for the DX 195 caliper. This kit replaces DSB3, DSB4 and DSB104.



MCK1171 Guide Pin Kit
Includes the components from the "old" kit DSB7, but now also includes piston seals.



New Service Kit information


MCK1192 Seal Kit

Worn or damaged seals previously replaced using DSB104 can now be more cost effectively replaced using this kit, which also includes grease and guide sleeve bolts.



MDP5076 Brake Pad Kit

Is a direct supersession from DSB2A. This includes all the necessary components required for replacing the Disc Pads, no changes in the components.



New Service Kit information

Recently we amended the prices of our replacement Service Calipers 15224836SR and 15224837SF effective from the 1st July 2003. As a consequence the Adjuster Kits DSB5L and DSB5R and the Thru Plate Kits DSB6L and DSB6R will no longer be available from the 1st November 2003 as it is now more economically viable to fit a new caliper than repair the old one with these internal components. From the same date DSB104 will also be discontinued, but the alternative kits MCK1168 and MCK1192 should be ordered accordingly.

An order for these “old” kits will be accepted up until the 31st October 2003 and then you must order your requirements for the new kits as illustrated.

If you currently have pending orders for the “DSB” references referred to in this communication and would like to make any amendments, please contact your Customer Service Representative.

Prices shown on the attached list are effective from 1st November 2003 and valid until further notice.

Early DX195 – 25/26 calipers have old style components, which may not be fully serviceable by these kits. Please call your Meritor Technical Helpline for information.

**List Prices as from the 1st November 2003 for the
DX 195 Service Caliper and Kits**

Part Number	Description	List Price
15224836SR	Service Caliper	£ 500.00
15224837SR	Service Caliper	£ 500.00
MCK1160	Lever Kit	£ 16.50
MCK1161	Lever Kit	£ 16.50
MCK1168	Eccentric Shaft Kit	£ 88.00
MCK1171	Slide & Seal Kit	£ 91.00
MCK1192	Seal Kit	£ 46.00
MDP5076	Brake Pad Kit	£ 106.25